Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: BLDU DD-308

Field Name: BEAVER LODGE Well File #: 14940

Date Incident:6/20/2015Time Incident:10:40Facility ID Number:County:WILLIAMSTwp:155Rng:96Sec:2Qtr:

Location Description: PSV popoff released south southeast impacting a total area of 11,150 sq. ft.

(650 sq. ft On Location and 10,500 sq. ft. Off Location)

Submitted By: Troy Brunsell Received By:

Contact Person: Jason Henry

1501 MCKINNEY HOUSTON, TX 77010

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Treater Popoff

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine

Other 2.2 Barrels

Description of Other Released Contaminant:

Emulsion

Inspected: Written Report Received: 3/4/2016 Clean Up Concluded: 7/17/2015

Risk Evaluation:

No immediate risk to report at this time.

Areal Extent:

Off location South Southeast in cropland.

Potential Environmental Impacts:

Topsoil both on / off location.

Action Taken or Planned:

Location has been taged out of service until repairs are completed. Impacted area will be cleaned up and disposed of.

Wastes Disposal Location: An Approved Waste Facility.

Agencies Involved:

Updates

Date: 6/22/2015 Status: Reviewed - Follow-up Required Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to treater popoff, was not contained on location according to the report. Followup is necessary.

Date: 8/13/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 16:36 8/13/2015.

Minimal impacts to areas off of location. Impacted soil has been removed.

No followup is necessary.